



TIPOS DE TERMINAL


Terminal T1
FASTON TYPE




Terminal T5
Torque: 3.9 ~ 5.4 N*m




Terminal T10
Torque: 3.9 ~ 5.4 N*m




T14-1 Positive
Torque: 11 ~ 14.7 N*m




Terminal T2
FASTON TYPE




Terminal T6
Torque: 3.9 ~ 5.4 N*m




Terminal T11
Torque: 11 ~ 14.7 N*m




Spring Terminal
Fully Collapsible




Terminal T3
Torque: 3.9 ~ 5.4 N*m




Terminal T7
Torque: 3.9 ~ 5.4 N*m




Terminal T12
Torque: 2.0 ~ 3.0 N*m




Connector
H-Connector




Terminal T4



Terminal T9
Torque: 11 ~ 14.7 N*m



Terminal T13
Torque: 3.9 ~ 5.4 N*m



Tipos de Terminal y posiciones

